



# SERVICE LETTER

No. 832

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

"DOA SO-1 Approved"

January 25, 1978

S

Subject: Wheel Well Reinforcement

Models Affected:

Serial Numbers Affected:

PA-28R-180 Cherokee .....	28R-30004 to 28R-7130013 Inclusive
PA-28R-200 Cherokee Arrow II .....	28R-35001 to 28R-7635545 Inclusive
PA-28R-201 Cherokee Arrow III .....	28R-7737002 to 28R-7737135 Inclusive
PA-28R-201T Cherokee Turbo Arrow III ...	28R-7703001 to 28R-7703314 Inclusive

Compliance Time: At owner/operator's discretion.

Purpose: The possibility exists when jacking up the aircraft under certain loading conditions that buckling may occur in the firewall when the forward jacking pad is utilized.

To alleviate this condition a wheel well stiffener kit has been developed that when installed will provide additional reinforcement of the wheel well area.

Instructions: The instructions necessary to install this product refinement are contained in Kit, Part No. 763 805V.

Material Required: One (1) Modification-Wheel Well Stiffener Kit, Piper Part No. 763 805V @ suggested unit list price \$4.73.

Availability of Parts: Your Piper Field Service Facility.

Effectivity Date: This Service Letter is effective upon receipt.

Summary: Please contact your Piper Field Service Facility to make arrangements to incorporate this product refinement feature on your aircraft.