



# SERVICE LETTER

No. 920

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

June 29, 1981

S/M

Subject:

Required Placard Adhesion Check

Models Affected:

Serial Numbers Affected:

PA-28-161 Warrior II  
PA-28-181 Archer II  
PA-28-201T Turbo Dakota  
PA-28-236 Dakota  
PA-28R-201 Arrow III  
PA-28RT-201 Arrow IV  
PA-28R-201T Turbo Arrow III  
PA-28RT-201T Turbo Arrow IV  
PA-32-260 Six 260  
PA-32-300 Six 300  
PA-32-301 Saratoga  
PA-32-301T Turbo Saratoga  
PA-32R-300 Lance  
PA-32RT-300 Lance II  
PA-32RT-300T Turbo Lance II  
PA-32R-301 Saratoga S.P.  
PA-32R-301T Turbo Saratoga S.P.  
PA-34-200T Seneca II  
PA-34-220T Seneca III  
PA-44-180 Seminole  
PA-44-180T Turbo Seminole

28-7816001 through 28-8116183  
28-7890001 through 28-8190193  
28-7921001 through 28-7921091  
28-7911001 through 28-8111055  
28R-7837001 through 28R-7837317  
28R-7918001 through 28R-8118058  
28R-7803001 through 28R-7803373  
28R-7931001 through 28R-8131099  
32-7800001 through 32-7800008  
32-7840001 through 32-7840290  
32-8006002 through 32-8106050  
32-8024001 through 32-8124018  
32R-7880001 through 32R-7880068  
32R-7885001 through 32R-7985105  
32R-7887002 through 32R-7987126  
32R-8013001 through 32R-8113051  
32R-8029001 through 32R-8129053  
34-7870001 through 34-8170092  
34-8133001 through 34-8133041  
44-7995001 through 44-8195017  
44-8107001 through 44-8107045

Compliance Time:

Recommended at the next regularly scheduled inspection event. Owner/pilot may accomplish this inspection and/or replacement

Purpose:

Reports have been received of loose and peeling operational placards in the cockpits of the aircraft listed above.

This Service Release announces the availability of placards with an improved adhesive.

(over)

Instructions:

1. Determine applicable placards from aircraft P.O.H. or A.F.M. Limitation Section.

NOTE: Operational placards for optional equipment (Autopilots, Avionics, etc.) may be found in the Limitations Section for that particular installation, see the appropriate Supplement in the P.O.H. or A.F.M.

2. Replace loose and peeling operational placards as required.
3. Make appropriate logbook entry of compliance with this Service Release.

Material Required:

Applicable placards as defined by the aircraft P.O.H. or A.F.M.

Effectivity Date:

This Service Release is effective upon receipt.

Estimated Labor Requirement: (For Planning Purposes Only)

Approximately one (1) hour will be required for the inspection and subsequent replacement of placards.

Summary:

Please contact your Piper Field Service Facility to make arrangements for compliance with the provisions of this Service Release in accordance with Compliance Time, indicated.

Any applicable Factory Participation will remain in effect for a period of time not to exceed 180 days from the date of this Service Release.